

FILE NOTATIONS

Entered In NID File

Entered On S R Sheet

Location Map Pinned

Card Indexed

I W R for State or Fee Land

✓
✓
✓
✓

Checked by Chief

Copy NID to Field Office

Approval Letter

Disapproval Letter

✓
✓
✓
✓

COMPLETION DATA:

Date Well Completed 1-8-59

OW _____ WW _____ TA _____

GW _____ OS _____ PA ✓

Location Inspected

Bond released

State of Fee Land

✓ 2-27-59 - NCH

LOGS FILED

Driller's Log _____

Electric Logs (No.) 1

E _____ I _____ E-I ✓ GR _____ GR-N _____ Micro _____

Lat. _____ Mi-L _____ Sonic _____ Others _____

			X
Sec.	1		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No.

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	X	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 10, 19 57

Columbus Rexall
Well No. 1 is located 660 ft. from ~~N~~ line and 660 ft. from ~~E~~ line of sec. #1
~~NE~~ of 1 41 S 18 E SLBM
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Mexican Hat San Juan County Utah
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5,005 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Operator will drill 12½" hole to a depth of 150' and set 150' of 10 3/4", 44# Casing with cable tools. Wet cement will be circulated to surface. From 150' to 3,000' or Pre-Cambrian with Rotary Equipment.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SERVICE OIL CO.

Address 1240 First Security Bldg.

Salt Lake City, Utah

By *Robert J. Hyde*

Title Attorney-in-Fact

SAN JUAN SURVEYING SERVICE
MONTICELLO, UTAH
APRIL 12, 1957

NOTE: ALL SECTION CORNERS AND
QUARTER CORNERS FOUND ARE SHOWN.

SCALE 1"=200'

NE 1/4 OF NE 1/4
SECTION 1

RANGE 18 E

NOTE: SET 2"X2"X16'
POLE WITH YELLOW FLAG

WELL SITE

ELEV. 4595

660

REG. LAND SURVEYOR NO. 1361

April 24, 1957

863 Service Oil Company
805 1st Security Building
Salt Lake City, Utah

Gentlemen:

It has come to the attention of this office that you intend drilling a well in the NE 1/4 of Section 6, Township 40 South, Range 18 East, S1EM, San Juan County, Utah.

Under the General Rules and Regulations adopted by the Utah Oil & Gas Conservation Commission, any individual or corporation intending to drill for oil and/or gas in the State of Utah must file a notice of intention to drill with this office and have said notice approved by the Commission before spudding in except for those cases which fall under Rule A-3 of these rules and regulations.

It would appear that this well does not fall within the exception provided for under Rule A-3.

Therefore, prior to commencement of drilling operations on this well, you are requested to file a notice of intention to drill with this office and have the same approved.

There is enclosed herewith a copy of our rules and regulations and some of our Forms OCGC-1, Notice of Intention to Drill, for your information and use.

Yours very truly,

OIL & GAS CONSERVATION COMMISSION

CLEON B. FREIGHT
SECRETARY

CBF:en

May 21, 1957

Service Oil Company
863 1st Security Building
Salt Lake City, Utah

Gentlemen:

On April 24, 1957, the following letter was sent to you by this office:

"It has come to the attention of this office that you intend drilling a well in the NW $\frac{1}{4}$ NE $\frac{1}{4}$ of Section 6, Township 40 South, Range 15 East, SEEM, San Juan County, Utah.

Under the General Rules and Regulations adopted by the Utah Oil and Gas Conservation Commission, any individual or corporation intending to drill for oil and/or gas in the State of Utah must file a notice of intention to drill with this office and have said notice approved by the Commission before spudding in except for those cases which fall under Rule A-3 of these rules and regulations.

It would appear that this well does not fall within the exception provided for under Rule A-3.

Therefore, prior to commencement of drilling operations on this well, you are requested to file a notice of intention to drill with this office and have the same approved.

There is enclosed herewith a copy of our rules and regulations and some of our Forms GOCG-1, Notice of Intention to Drill, for your information and use."

Please advise.

Yours very truly,

OIL & GAS CONSERVATION COMMISSION

GLENN B. FREIGHT
SECRETARY

CBF:em

cc: Three States Natural Gas Co.
Box 67
Farmington, New Mexico

Reynolds Mining Company
Box 1328, Durango, Colorado

LAW OFFICES OF
GORDON I. HYDE
SUITE 863
FIRST SECURITY BUILDING
405 SOUTH MAIN STREET
PHONE ELGIN 5-5381
SALT LAKE CITY, UTAH

May 22, 1957

*Put in General
Correspondence number
Service Oil Co. 7*

The State of Utah
Oil & Gas Conservation Commission
Salt Lake City 14, Utah

Attention, Mr. Cleon B. Feight, Secretary

Dear Mr. Feight:

Your letter directed to Service Oil Company,
dated May 21, 1957, has been referred to me.

In your letter you say it has come to your
attention that we intend to drill a well in San Juan
County, all of which is the case.

We will obtain the necessary approval at the
time we are ready to commence drilling. We are
fully aware of your regulations.

Very truly yours,


Gordon I. Hyde

GIH b

May 23, 1957

Service Oil Company
1240 First Security Building
Salt Lake City, Utah

Gentlemen:

This is to acknowledge receipt of your notice of intention to drill Well No. Columbus Rexall 1, which is to be located 660 feet from the north line and 660 feet from the east line of Section 1, Township 41 South, Range 18 East, S1E4N, San Juan County, Utah.

Please be advised that insofar as this office is concerned, approval to drill said well is hereby granted.

However, said approval is conditional upon a plat being submitted in accordance with Rule C-4, General Rules and Regulations and Rules of Practice and Procedure, Oil and Gas Conservation Commission, State of Utah.

Yours very truly,

OIL & GAS CONSERVATION COMMISSION

GLENN B. FEIGHT
SECRETARY

GBF:en

cc: Phil McGrath/ Jerry Long
U.S.G.S. Farmington,
New Mexico

LAW OFFICES OF
GORDON I. HYDE
SUITE 863
FIRST SECURITY BUILDING
405 SOUTH MAIN STREET
PHONE ELGIN 5-5381
SALT LAKE CITY, UTAH

May 25, 1957

Oil and Gas Conservation Commission
State Capitol Building
Salt Lake City, Utah

Attention, Mr. Cleon B. Feight, Secretary

Dear Mr. Feight:

Mr. John Archer has referred to me your letter directed to Service Oil Corp., and dated May 23, 1957, in which you request a plat be submitted in accordance with Rule C-4.


In referring to Rule C-4 I find that the rule provides that a plat or map be submitted showing the location of all leases, property lines, drilling and producing wells within an area of sufficient size so that the Commission may determine whether the location of the well conforms to the applicable rules, regulations, and orders.

There is no producing well or drilling operation within several miles of this property. The location is 660 feet from the North line and 660 feet from the East line of the legal subdivision indicated on the Notice of Intention to Drill. All of the leases are Federal leases.

I would appreciate your letting me know the type of additional information, if any, that you need. We can outline on a plat the outline of the surrounding leases. We, however, are the owners of these leases in conjunction with our associates, and there would be no other lease owners within a half mile of this location.

Enclosed is a copy of the surveyed location.

Very truly yours,


Gordon I. Hyde

GIH b

May 27, 1957

Gordon I. Hyde, Attorney at Law
Suite 863, First Security Building
405 South Main Street
Salt Lake City, Utah

Dear Sir:

This is to acknowledge receipt of the Surveyor's Plat for
Service Oil Corporation, Well No. Columbus Rexall 1,
Section 1, Township 41 South, Range 18 East, SLPM, San Juan
County.

Thank you very much.

We need no additional information.

Yours very truly,

OIL & GAS CONSERVATION COMMISSION

OLEON B. FREIGHT
SECRETARY

GBF:cn

**reports*
get logs from ~~Russell~~ McGrath

February 18, 1958

Service Oil Company
1240 First Security Building
Salt Lake City, Utah

Re: Well No. Columbus Rexall 1,
Sec. 1, T. 41 S, R. 18 E,
SEEM, San Juan County, Utah

Gentlemen:

This letter is to advise you that the well log for the above mentioned well has not as yet been filed with this office as required by our rules and regulations.

Please complete the enclosed forms OGOC-3, Log of Oil or Gas Well, in duplicate, and forward them to this office as soon as possible.

Yours very truly,

OIL & GAS CONSERVATION COMMISSION

OLEON B. FREIGHT
SECRETARY

CBF:cn

Encl.

May 16, 1958

Service Oil Company
1240 First Security Building
Salt Lake City, Utah

Re: Well No. Columbus Rexall 1,
Sec. 1, Twp. 41 S, R. 18 E,
SEPM, San Juan County, Utah

Gentlemen:

This letter is to advise you that the well log for the above mentioned well has not as yet been filed with this office as requested in our letter of February 18, 1958.

This well log is now four months past due.

Please complete the enclosed forms OCGG-3, Log of Oil or Gas Well, in duplicate, and forward them to this office as soon as possible.

Yours very truly,

OIL & GAS CONSERVATION COMMISSION


OLEON B. FREIGHT
SECRETARY

CBF:en

Encls.

El log filed - Dec. '58

Gordon Hyde ?



STATE OF UTAH
OIL & GAS CONSERVATION COMMISSION

STATE CAPITOL BUILDING
 SALT LAKE CITY 14, UTAH

Fee and Patented.....☐
 State Utah.....☐
 Lease No. 022136.....
 Public Domain☐
 Lease No.
 Indian☐
 Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

Notice of Intention to Drill..... Notice of Intention to Change Plans..... Notice of Intention to Redrill or Repair..... Notice of Intention to Pull or Alter Casing..... Notice of Intention to Abandon Well.....	<input checked="" type="checkbox"/>	Subsequent Report of Water Shut-off..... Subsequent Report of Altering Casing..... Subsequent Report of Redrilling or Repair..... Supplementary Well History.....
--	-------------------------------------	--

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 3, 1958

Well No. 1 is located 660 ft. from {N} line and 660 ft. from {E} line of Sec. 1
NE $\frac{1}{4}$ NE $\frac{1}{4}$ - 1 41 So. 18 E. S.L.M.
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Mexican Hat San Juan Utah
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is feet.

A drilling and plugging bond has been filed with

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important work, surface formation, and date anticipate spudding-in.)

Cementing Intervals:

From	To
2900'	2700'
2450'	2250'
2050'	1900'
1750'	1050'
400'	300'

El log = 2799'

Set Regulation Pipe Marker as per Reg. #221.22 with Well Name, Sec., TWP, Range, Etc.

I understand that this plan of work must receive approval in writing by the Commission before operations may be commenced.

Company SERVICE OIL CORP.

Address 863 First Security Bldg.
Salt Lake City 11, Utah

By

Gordon I. Hyde
 Gordon I. Hyde

Title

Secretary

INSTRUCTIONS: A plat or map must be attached to this form showing the location of all leases, property lines, drilling and producing wells, within an area of sufficient size so that the Commission may determine whether the location of the well conforms to applicable rules, regulations and orders.

December 15, 1958

Mr. Phil T. McGrath,
District Engineer
U. S. Geological Survey
Farmington, New Mexico

Re: Well No. Columbus-Rexall 1,
NE 1-41S-18E, SLM, San Juan
County, Utah

Dear Phil:

We have made several attempts to secure reports on the above operations by the Service Oil Company and have met with not too much success. The last attempt was to obtain a log on our Form OGCC-3 on the well but, in lieu of that apparent log, he has submitted a strip log without giving his tops.

We are advised that the Moab Drilling Company of Moab has plugged, or is planning to plug, this well. We feel that this plugging operation should be witnessed by either your office or this office in as much as their past operations have needed checking.

We will appreciate your advising us whether or not this plugging has been, or is to be, performed, and if you are unable to have a witness present at the time the work is done, we would like to arrange with the operator to be present when the plugging work is performed.

Yours very truly,

OIL & GAS CONSERVATION COMMISSION

CHAS. A. HAUPTMAN
PETROLEUM ENGINEER

GAH:co

12-31-58

Phil McGrath called and said that Service oil was not yet ready to plug.

oat

STATE OF UTAH
OIL AND GAS CONSERVATION COMMISSION

AFFIDAVIT AND RECORD OF ABANDONMENT AND PLUGGING

11-18
1-19-59

PLUGGING METHODS AND PROCEDURE: --The method and procedure for plugging a well shall be as follows:

- (a) The bottom of the hole shall be filled to, or a bridge shall be placed at the top of each producing formation open to the well bore, and in either event, a cement plug not less than fifty (50) feet in length shall be placed immediately above each producing formation open to the well bore whenever possible.
- (b) A cement plug not less than fifty (50) feet in length shall be placed at approximately fifty (50) feet above and below all fresh water bearing strata.
- (c) A plug shall be placed at or near the surface of the ground in each hole.
- (d) The interval between plugs shall be filled with heavy mud-laden fluid.
- (e) The hole shall be plugged with heavy mud up to the base of the surface string at which point a plug of not less than fifty (50) feet of cement shall be placed.

Field or Pool Mexican Hat County San Juan
Lease Name Hyde Well No. 1 Sec. 1 Twp 13S R. 18E
Date well was plugged: January 8, , 19 59 .

Was the well plugged according to regulation of the Commission: _____

Set out method used in plugging the well, the nature and quantities of materials used in plugging, size of plugs, location and extent (by depths) of the plugs of different materials, and the amount of casing left in hole, (giving size, top and bottom elevations of each section of abandoned casing).

Halliburton Oil Well Cementing Co., mixed and pumped 265 sacks, Type 1 regular cement through open end drill pipe. Set six(6) plugs (2900'-2700'-63sacks) 2450'-2250'-63 sacks) (2050'-1900'-47 sacks) (1150'-1050'-33 Sacks) (400'-300'-33 sacks) (150'-100'-26 sacks) (150' Of 10 3/4" O.D. surface casing- ground level to 150')

Operator Moab Drilling Co.

Address Box 487

Moab, Utah

AFFIDAVIT

STATE OF UTAH

COUNTY OF San Juan

Before me, the undersigned authority on this day personally appeared Mr. D. P. Piroon, Moab Drilling Co., known to me to be the person whose name is subscribed to the above instrument, who being by me duly sworn on oath states that he is authorized to make this report and has knowledge of the facts stated herein, and that said report is true and correct.

Subscribed and sworn to before me this 13 day of January, 1959.

My Commission Expires: 12-27-61

Margie D. Shaper
NOTARY PUBLIC

INSTRUCTIONS: Complete this form, in duplicate, and mail both copies to the Oil & Gas Conservation Commission, Room 140, State Capitol Building, Salt Lake City 14, Utah.

W

Check w/ McGeath
on letter to him
of Dec 15

Per visit, WYMEY

Haliburton well-Co.
1-8-59. Farmington
drilled by Moab Drilling Co. Co.,
a complete report on setting of
plugs in this well

January 19, 1939

Mr. Gordon Hyde, Secretary
Service Oil Company
863 First Security Building
Salt Lake City 11, Utah

Re: Well No. Federal 1,
NE Sec. 1, T. 41 S, R. 18 E,
S.L.B.M., San Juan County

Dear Sir:

In checking our files we note that we have on two previous occasions, February 18 and May 16, 1938, called on you for a detailed log (our Form OGOC-3), but without success.

We have received from you a reproduced copy of the electric log of the well, sand formation tops, etc. Submission of this does not meet all regulation requirements, and is not acceptable as a substitute for Form OGOC-3.

Unless prompt compliance is made as above requested, definite restrictive action or further operations by you, will of necessity, be taken by this Commission.

Blank Forms OGOC-3 are attached for your use.

Yours very truly,

OIL & GAS CONSERVATION COMMISSION

CHES. A. HAUPTMAN
PETROLEUM ENGINEER

CAN:co

Encls. (Forms 3)

June 23, 1961

Service Oil Co.
% Gordon I. Hyde
863 First Security Bldg.
Salt Lake City, Utah

Gentlemen:

After checking over the reports submitted on the following wells, we have found that our files are incomplete. According to our records, your Log of Oil & Gas Well has not been filed in accordance with Rule C-5 (a) of our rules and regulations:

Well no. COLUMBUS REXALL 1
Sec. 1, T. 41 S, R. 18 E.
San Juan County, Utah

A Log of Oil & Gas Well should have been filed with this Commission within ninety days after the suspension of operations on, abandonment of, or the completion of any wells drilled for the production of oil and gas. Therefore, we are requesting that you complete the enclosed Forms OGCC-3, Log of Oil or Gas Well, in duplicate, for said well.

Your assistance in this matter will be greatly appreciated.

Yours very truly,

OIL & GAS CONSERVATION COMMISSION

ANN W. GLINES
RECORDS CLERK

AWG/jc

*Mr. Gordon Hyde came in the office and ask us to obtain the
Copy of the Driller's Log from Moab Drilling Co., Moab,
Utah.*

November 22, 1961

Moab Drilling Company
Moab, Utah

Re: Well No. Columbus Rexall 1
Sec. 1, T. 41 S., R. 18 E.
San Juan County, Utah

Gentlemen:

After checking over the reports submitted on the above mentioned well, we found that our file was incomplete in that no Log Of Oil Or Gas Well had been submitted. Therefore, we wrote to Mr. Gordon I. Hyde, Salt Lake City, and he referred us to you.

We are enclosing copies of our Form OGCC-3 and hope that you will be able to complete this and return to us.

Your help and assistance in this matter will be greatly appreciated.

Very truly yours,

OIL & GAS CONSERVATION COMMISSION

ANN W. GLINES,
RECORDS CLERK

AWG:kp
Encl.

October 11, 1962

Moab Drilling Company
1790 East Plumb Lane
Reno, Nevada

Re: Well No. Columbus-Rexall #1
Sec. 1, T. 41 S, R. 18 E.,
San Juan County, Utah

Gentlemen:

Reference is made to our letter of November 22, 1961, regarding the "Log of Oil or Gas Well" Form OGCC-3, for the above mentioned well as we were referred to you by Mr. Gordon I. Hyde, Salt Lake City. However, upon checking our file again, we note that we still have not received the above report.

It would be greatly appreciated if you could furnish us with this information in order that we may complete our file on said well.

We are enclosing copies of Form OGCC-3 for your convenience. Thank you for your immediate attention in this matter.

Very truly yours,

OIL & GAS CONSERVATION COMMISSION

CONNIE F. PALOUKOS
RECORDS CLERK

CFP:cnp

December 24, 1962

Moab Drilling Company
1790 East Plumb Lane
Reno, Nevada

Re: Well No. Columbus-Rexall #1
Sec. 1, T. 41 S, R. 18 E.,
San Juan County, Utah

Gentlemen:

Reference is made to our letters of November 22, 1961 and October 11, 1962, regarding the "Log of Oil or Gas Well", Form OGCC-3, for the above mentioned well as we were referred to you by Mr. Gordon I. Hyde, Salt Lake City, Utah. As of this date, we still have not received the above mentioned report as required by our rules and regulations.

Please complete the enclosed Forms OGCC-3 in duplicate and forward them to this office as soon as possible. Legible copies of the U. S. Geological Survey Form 9-330 may be used in lieu of our forms.

Your immediate attention to the above request will be greatly appreciated.

Very truly yours,

OIL & GAS CONSERVATION COMMISSION


CONNIE F. PALOUKOS
RECORDS CLERK

GFP:cnp

cc: Service Oil Company
c/o Gordon I. Hyde
863 First Security Building
Salt Lake City, Utah

Encl. (Forms)

8



Charles A. Steen Company • 1790 E. PLUMB LANE • RENO, NEVADA • 32 94216

CHARLES A. STEEN, PRESIDENT, CHIEF GEOLOGIST
MINERAL EXPLORATION AND DEVELOPMENT • DRILLING CONTRACTORS
MAX D. PIERSON, GENERAL MANAGER

January 3, 1963

The State of Utah
Oil and Gas Conservation Commission
310 Newhouse Building
10 Exchange Place
Salt Lake City 11, Utah

ATTN: Connie F. Paloukos
Records Clerk

RE: Columbus Rexalt # 1
Sec. 1, 41S, 18E
San Juan Co., Utah

Dear Sirs:

This office has received your two letters regarding the above well. This matter predates my employment with Moab Drilling, but I do remember when this well was drilled.

This is what I know, Mr. Gordon Hyde and Mr. John Archer formed a collapsible corporation and were the operators. They never paid Moab Drilling for this job. Mr. Steen sued and I suppose the courts got what records we had as I can find none now.

There must have been some dry-hole money due the operators, but the courts awarded it to Moab Drilling, but with the understanding that Moab Drilling clean the location, plug and abandon, and mark the hole.

Mr. Steen sent me to Farmington, New Mexico, to pick up a United States Geological Survey geologist, fly him to the location to approve the site, and bring written approval back to Moab.

It seems this matter should be taken care of by Mr. Hyde or Mr. Archer.

Sincerely,

Max D. Pierson
General Manager

MDP:ch